

### UNITED STATES ENVIRONMENTAL PROTECTION AGENCY REGION III 1650 Arch Street Philadelphia, Pennsylvania 19103-2029

August 14, 2013

Ms. Michelle Falesch Enercon Services, Inc. 2056 Westings Avenue Suite 140 Naperville, IL 60503

Re: Freedom of Information Act Request: EPA-R3-2013-7816

Dear Ms. Falesch:

This is in response to your Freedom of Information Act request listed above, regarding 3700 Pennsylvania Avenue Property.

/X / The Office Of Hazardous Site Clean-up Division is enclosing records in response to your request.

/ / The Resource Conservation and Recovery Program, the Toxics Programs Branch, and the Pesticides/Asbestos Programs Branch found no records in response to your request.

/ / The Water Protection Division found no records in response to your request.

PLEASE NOTE:

If any Program(s) listed above has been checked, a response from that Program(s) <u>is</u> enclosed along with a billing invoice for the information provided if appropriate.

You may appeal this response to the National Freedom of Information Officer, U.S. EPA Records, FOIA and Privacy Branch, 1200 Pennsylvania Avenue, NW (2822T), Washington, DC 20460, Fax: (202) 566-2147, E-mail: <a href="https://hq.foia@epa.gov">https://hq.foia@epa.gov</a>. Only items mailed through the United States Postal Service may be delivered to 1200 Pennsylvania Avenue, NW. If you are submitting your appeal via hand delivery, courier service or overnight delivery, you must address your correspondence to 1301 Constitution Avenue, N.W., Room 6416J, Washington, DC 20004. Your appeal must be made in writing and it must be submitted no later than 30 calendar days from the date of this letter. The Agency will not consider appeals received after the 30 calendar day limit. The appeal letter should include the EPA-R3 number listed above. For quickest possible handling, the appeal letter and its envelope should be marked "Freedom of Information Act Appeal."

If you have any questions, please contact me at 215-814-5553.

Sincerely,

Richard Van Holt

Freedom of Information Officer

# SITE/RESPONSE ACTION LISTING (CERCLIS) (LIST-08), VERSION 10.00

THIS IS THE \*\* PRODUCTION VERSION \*\* OF THE REPORT

**USER SELECTION OPTIONS** 

REGION:

CERCLIS REPORT TYPE:

Integrated PROGRAM AREA: SELECT CRITERIA:

Zip Code = 26062 Region, EPA ID SCREEN SORT BY:

**OUTPUT DESTINATION:** 

\*\* PRODUCTION VERSION \*\*
U.S. EPA SUPERFUND PROGRAM

CERCLIS DATABASE LATE: 07/25/2013 CERCLIS DATABASE TIME: 11:02:20

VERSION: 10.00

RUN DATE: 07/25/2013 11:02:20

CERCLIS

Site/Response Action Listing (CERCLIS)

(LIST-08 CERCLIS)

33 Region:

			Region: 03				
	SITE NAME						
	STREET			1	ACTUAL	ACTUAL	
	CITY	STATE ZIF	ZIP OP ACTION	ACTION	START	COMPLETE	ACTION
SITE ID EPAID NO.	COUNTY (FIPS) CODE AND NAME	CONG DIST. UNIT	UNIT CODE, NAME	SEQ QUALIFIER	DATE	DATE	LEAD
0303020 WVD98053	0303020 WVD980538507 NATIONAL STEEL CORP						
	POB 431		NON-NPL STATUS:	NFRAP-Site does not qualify for the NPL based on existing information	e NPL based	on existing info	rmation
	WEIRTON 54029 HANCOCK	WV 26062 01	2 ASSOCIATED SITE: 1 ASSOCIATED EPA ID:	N/A			
			00 DS DISCVRY	001		09/01/1979	EPA Fund
			00 PA PA	001 Low priority		03/01/1980	State (Fund)
	202200000		00 SI SI	001 NFRAP 0	03/01/1980	03/01/1980	State (Fund)
	a de la companya de		00 SH SiteInspPrior	002 NFRAP 0	01/05/1993	03/30/1993	State (Fund)
	and the state of t		00 SI SI	001 NFRAP 0	03/01/1980	03/01/1980	State (Fund)
			00 SH SiteInspPrior	001 NFRAP		03/30/1993	State (Fund)
			00 VS ARCH SITE	001		03/30/1993	EPA In-House
	e de la compact		00 VU UNARCHIVE	001		04/30/2004	EPA In-House
0305701 WVN000305701	05/01 US FILTER WEIRTON STEEL OUTFALL 004 CH	L 004 CHEMICAL SPILL	PILL				
	400 THREE SPRINGS DRIVE		NON-NPL STATUS:	Removal Only Site (No Site Assessment Work Needed)	sment Work N	(eeded)	
	WEIRTON	WV 26062		N/A			
	54029 HANCOCK	01	1 ASSOCIATED EPA ID:				
			00 RS RV ASSESS	001	09/13/2001	10/19/2001	EPA Fund
	d Sudde Sta		00 PJ RP EM REM	001 Stabilized 0	09/13/2001		PRP Rsp Fed
0305890 WVN000305390	05390 WEIRTON STEEL CHROMIC ACID SPILLS	ILLS					
	4003 SPRING DRIVE		NON-NPL STATUS:	SI Start Needed			
	WEIRTON	WV 26062	2 ASSOCIATED SITE:	N/A			
	54029 HANCOCK	01	1 ASSOCIATED EPA ID:				
	····		00 DS DISCVRY	001		05/13/2002	EPA Fund
			00 RS RV ASSESS	001	05/13/2002	06/11/2002	EPA Fund
	Odos Fess		00 PA PA	001 Low priority 1	11/30/2004	12/30/2004	State (Fund)

ო TOTAL NUMBER OF SITES IN REPORT:

### REGION IS 1660 Arch Street

Philadelphile, Fennsylvania 18183-2029

Enclosed please find report(s) containing the data you requested from the Emergency Response Notification System (ERMS)

The data includes the notification for:

03-FOI-18/10 -/3

following are REY CODES necessary to interpret some of the fields

MEDIUM AFFECTED:

A-AIR, L-LAND, M-WATER, G-GROUNDWATER, E-WITHIN FACILITY, O-OTHER, U-UNKNOWN

**SOURCE:** 

A-AIR TRANSPORT, F-FIXED FACILITY, H-HIGHWAY, V-VESSEL, G-OFFSHORE, F-FIFELINE, R-RAILWAY, T-ABOVE GROUND STORAGE TANK, S-UNDERGROUND STORAGE TANK, S-UNDERGROUND

CAUSE:

U-DUMPING, E-OPERATIONAL ERROR, F-EQUIPMENT FRILDRE, H-NATURAL PHENCHENON, T-TRANSPORTATION ACCIDENT, G-OTHER, U-UNKNOWN

For any problems and/or questions, please notify: Linda Marzulli at 215-814-3256

PLEASE NOTE THAT THIS IS AN INITIAL NOTIFICATION DATA ONLY AND MAY BE SUBJECT TO VERIFICATION.

Please Note: This information is initial notification data and may be subject to verification.

Incident Notification No.: UNKNOWN SHEEN 1008745 Incident Type: Incident Date: Incident Cause: UNKNOWN Affected Medium **Incident Location** 3031 BIRCH DRIVE Waterway: OHIO RIVER Medium: WATER NULL NULL Tributary to: NULL WIRTON City\*: Additional Medium Info: OHIO RIVER State: WV Zip: 26062 County: BROOKE \* Nearest City to Incident location is given. Incident may not have occurred within city borders. Spilled Material: **UNKNOWN OIL** Quantity: 0 Units: UNKNOWN AMO Potential Response Party First Name: NULL Company: NULL UNKNOWN UNKNOWN Last Name: Type: Incident Notification No.: Incident Type: 986233 UNKNOWN SHEEN **Incident Date:** Incident Cause: 8/17/2011 UNKNOWN Affected Medium Incident Location 3048 BIRCH DR Medium: WATER Waterway: OHIO RIVER NULL NULL Tributary to: NULL City\*: WEIRTON Additional Medium Info: OHIO RIVER 26062 State: WV Zip: County: BROOKE \* Nearest City to Incident location is given. Incident may not have occurred within city borders. **UNKNOWN OIL** Quantity: 0.00 UNKNOWN AMO Spilled Material: Units: Potential Response Party First Name: NULL Company: NULL UNKNOWN UNKNOWN Type: Last Name: Incident Notification No.: Incident Type: **FIXED** 949812 Incident Date: **Incident Cause:** 8/2/2010 DUMPING Incident Location Affected Medium UNKNOWN Medium: LAND Waterway: NULL NULL NULL NULL Tributary to: City\*: NULL Additional Medium Info: NULL State: WV Zip: 26062 County: BROOKE \* Nearest City to Incident location is given. Incident may not have occurred within city borders. UNKNOWN Quantity: 0.00 Units: UNKNOWN AMO Spilled Material: **Potential Response Party** TENDER TOUCH CAR WASH First Name: NULL Company:

PRIVATE ENTERPRISE

Type:

UNKNOWN

Last Name:

### Region III - Philadelphia PA

Please Note: This information is initial notification data and may be subject to verification.

**Incident Notification No.:** 568258 **FIXED** Incident Type: **Incident Date:** Incident Cause: 6/4/2001 **EQUIPMENT FAILURE Incident Location** Affected Medium 400 THREE SPRINGS DRIVE Medium: WATER Waterway: HARMON CREEK Tributary to: OHIO RIVER City\*: WEIRTON Additional Medium Info: HARMON CREEK Zip: 26062 State: WV County: BROOKE \* Nearest City to Incident location is given. Incident may not have occurred within city borders. HYDRAULIC OIL Spilled Material: Quantity: Units: 900.00GALLON( Potential Response Party First Name: DAVID Company: WEIRTON STEEL Last Name: MINDA Type: PRIVATE ENTERPRISE Incident Notification No.: **FIXED** 519104 Incident Type: Incident Date: Incident Cause: 1/13/2000 OTHER Incident Location Affected Medium 104 MEINDENHALL STREET Medium: OTHER Waterway: Tributary to: City\*: WEIRTON Additional Medium Info: WITHIN RESIDENCE 26062 State: WV Zip: County: BROOKE \* Nearest City to Incident location is given. Incident may not have occurred within city borders. MERCURY Spilled Material: UNT Quantity: Units: 0.00UNKNOWN Potential Response Party First Name: MARIE(JULIO/JO Company: Last Name: E-11YOS) MARTINEZ Type: PRIVATE CITIZEN Incident Notification No.: 803236 **UNKNOWN SHEEN** Incident Type: Incident Date: 7/6/2006 Incident Cause: UNKNOWN **Incident Location** Affected Medium Medium: WATER Waterway: OHIO RIVER Tributary to: City\*: WEIRTON Additional Medium Info: OHIO RIVER Zip: 26062 State: WV County: BROOKE \* Nearest City to Incident location is given. Incident may not have occurred within city borders.

Quantity: 0.00

Potential Response Party

UNKNOWN

Company.

Type:

UNKNOWN OIL

Spilled Material:

Last Name: UNKNOWN

First Name.

Units:

UNKNOWN AMO

Region III - Philadelphia PA

Please Note: This information is initial notification data and may be subject to verification.

**Incident Notification No.: Incident Date:** 

540368 8/29/2000

Incident Type: Incident Cause:

FIXED

**Incident Location** 

ROUTE 2 COVE RD.

**EQUIPMENT FAILURE** Affected Medium

Medium: WATER

Waterway: HARMON CREEK

City\*: WEIRTON

Zip: 26062 County: HANCOCK

Tributary to: State: WV

OHIO RIVER

Additional Medium Info: HARMON CREEK / OHIO RIVER

\* Nearest City to incident location is given. Incident may not have occurred within city borders.

Spilled Material:

Quantity:

0.00UNKNOWN Units:

First Name: DAVID Last Name: MINDA

Potential Response Party Company: WEIRTON STEEL

Type:

PRIVATE ENTERPRISE

**Incident Notification No.:** 

551124

**PIPELINE** 

Incident Date:

12/16/2000

Incident Type: Incident Cause:

**EQUIPMENT FAILURE** 

**Incident Location** 400 THREE SPRINGS DR.

Medium: WATER

Affected Medium Waterway: OHIO RIVER

City\*: WEIRTON

Zip: 26062 Tributary to:

County: HANCOCK

State: WV

Additional Medium Info: SOIL

\* Nearest City to Incident location is given. Incident may not have occurred within city borders.

Company:

Spilled Material:

Quantity:

Units: 3000.00GALLON(

First Name: KEN

Potential Response Party

WEIRTON STEEL

Last Name: ANDERSON

Type:

PRIVATE ENTERPRISE

**Incident Notification No.:** 

**Incident Date:** 

549329

Incident Type:

**PIPELINE** 

11/27/2000

Incident Cause:

**EQUIPMENT FAILURE** 

Incident Location 400 THREE SPRINGS DR.

Medium: WATER

**Affected Medium** 

City\*:

Waterway: PROCESS SEWER

WEIRTON

Tributary to:

LAGOON SYSTEM > OHIO RIVER

Zip: 26062 County: HANCOCK

State: WV

Additional Medium Info: PROCESS SEWER > LAGOON SYSTEM > OHIO

\* Nearest City to Incident location is given. Incident may not have occurred within city borders. Spilled Material:

400.00GALLON(

Quantity:

Units:

First Name:

Last Name: ANDERSON

Potential Response Party Company: WEIRTON STEEL

Type:

### Region III - Philadelphia PA

Please Note: This information is initial notification data and may be subject to verification.

Incident Notification No.:

547782

Incident Type:

UNKNOWN SHEEN

Affected Medium

Incident Date:

11/9/2000

Incident Cause: **UNKNOWN** 

Incident Location

Medium: WATER

Waterway: OHIO RIVER

City\*: WEIRTON

Zip:

26062

State: WV

Tributary to:

Additional Medium Info: OHIO RIVER

County: HANCOCK

\* Nearest City to Incident location is given. Incident may not have occurred within city borders.

Spilled Material:

UNKNOWN OIL UNT

Quantity:

0.00UNKNOWN Units:

Potential Response Party

First Name: DAVID

Company:

**WEIRTON STEEL** 

Last Name: MINDA

Type:

PRIVATE ENTERPRISE

Incident Notification No.:

Incident Date:

545254

Incident Type:

FIXED

10/15/2000

Incident Cause:

**EQUIPMENT FAILURE** 

Incident Location

400 THREE SPRINGS DR.

Affected Medium

Medium: WATER

Waterway: STORM DRAINS>OUTFALL

City\*: WEIRTON

26062

State: WV

Tributary to: OHIO RIVER

Additional Medium Info: STORM DRAIN>OUTFALL

Zip:

County: HANCOCK

\* Nearest City to Incident location is given. Incident may not have occurred within city borders.

Spilled Material:

OIL. MISC: LUBRICATING

Quantity:

2.00GALLON(S) Units:

Potential Response Party

Company: WEIRTON STEEL

Last Name: ANTHONY

Type:

PRIVATE ENTERPRISE

Incident Notification No.:

First Name: STAN

541459

**Incident Type:** 

**FIXED** 

Incident Date:

9/8/2000

Incident Cause: UNKNOWN

Incident Location

400 THREE SPRINGS DRIVE

Affected Medium

Medium: WATER

Waterway: OHIO RIVER

City\*:

WEIRTON

Zip:

26062

State: WV

Tributary to:

Additional Medium Info: OHIO RIVER

County: HANCOCK

\* Nearest City to Incident location is given. Incident may not have occurred within city borders.

Spilled Material:

GRAPHITE MATERIAL UNT

Quantity:

0.00UNKNOWN Units:

Potential Response Party

First Name: MARK

Company: WEIRTON STEEL CORP

Last Name:

VIGNOVIC

Type:

### Region III - Philadelphia PA

Please Note: This information is initial notification data and may be subject to verification.

Incident Notification No.: 542127 Incident Type: FIXED Incident Date: 9/14/2000 Incident Cause: **UNKNOWN** Affected Medium Incident Location 400 THREE SPRINGS DR. Medium: WATER Waterway: OHIO RIVER Tributary to: City\*: WEIRTON Additional Medium Info: OHIO RIVER Zip: 26062 State: WV County: HANCOCK \* Nearest City to incident location is given. Incident may not have occurred within city borders. "BLACK WATER" UNT 0.00UNKNOWN Spilled Material: Quantity: Units: Potential Response Party First Name: JOHN Company: WEIRTON STEEL Last Name: COLLINS PRIVATE ENTERPRISE Type: Incident Notification No.: 539788 Incident Type: FIXED Incident Date: 8/24/2000 Incident Cause: **EQUIPMENT FAILURE Incident Location** Affected Medium COVE ROAD Medium: WATER Waterway: HARMON CREEK Tributary to: OHIO RIVER City\*: WEIRTON Additional Medium Info: HARMON CREEK Zip: 26062 State: WV County: HANCOCK \* Nearest City to incident location is given. Incident may not have occurred within city borders. 0.00UNKNOWN HYDRAULIC OIL Spilled Material: Quantity: Units: Potential Response Party First Name: DAVID Company: WEIRTON STEEL Last Name: PRIVATE ENTERPRISE MINDA Type: Incident Notification No.: **PIPELINE** 534187 Incident Type: Incident Date: Incident Cause: 7/2/2000 EQUIPMENT FAILURE **Affected Medium** Incident Location 400 THREE SPRINGS DR. Medium: SOIL Waterway: Tributary to: City\*: WEIRTON Additional Medium Info: Zip: 26062 State: WV County: HANCOCK \* Nearest City to Incident location is given. Incident may not have occurred within city borders. WASTE PICKLE LIQUOR 300.00GALLON( Spilled Material: Quantity: Units: Potential Response Party First Name: KENNETH Company: WEIRTON STEEL ADEERSON PRIVATE ENTERPRISE Last Name: Type:

### Region III - Philadelphia PA

Please Note: This information is initial notification data and may be subject to verification. **Incident Notification No.:** 526495 **PIPELINE** Incident Type: Incident Date: **EQUIPMENT FAILURE** Incident Cause: 4/19/2000 Affected Medium **Incident Location** 400-THREE SPRINGS DR. Medium: LAND Waterway: Tributary to: WEIRTON City\*: Additional Medium Info: SOIL/PAVEMENT State: WV Zip: 26062 County: HANCOCK \* Nearest City to Incident location is given. Incident may not have occurred within city borders. Units: 100.00GALLON( Spilled Material: HYDROCHLORIC ACID Quantity: Potential Response Party Company: WEIRTON STEEL CORP. First Name: DAVID Last Name: MINDA Type: PRIVATE ENTERPRISE Incident Notification No.: 519522 FIXED Incident Type: Incident Date: 2/10/2000 Incident Cause: **EQUIPMENT FAILURE** 

Incident Location

400 3 SPRINGS DR.

Affected Medium

Medium: LAND

Waterway:

WEIRTON City\*:

Zip: 26062 State: WV

County: HANCOCK

Tributary to:

Additional Medium Info:

\* Nearest City to Incident location is given. Incident may not have occurred within city borders.

Spilled Material:

HYDROCHLORIC ACID

Quantity:

50.00GALLON(S) Units:

Potential Response Party DAVID Company: WEIRTON STEEL First Name:

Last Name:

MINDA

Type:

PRIVATE ENTERPRISE

Incident Notification No.:

540884

Incident Type:

**FIXED** 

Incident Date:

9/3/2000

Incident Cause:

**EQUIPMENT FAILURE** 

Affected Medium

**Incident Location** 

400 THREE SPRINGS DR.

Medium: WATER

Waterway: OHIO RIVER

WEIRTON City\*:

26062 Zip:

State: WV

Tributary to:

**Additional Medium Info:** 

County: HANCOCK

\* Nearest City to Incident location is given. Incident may not have occurred within city borders. Spilled Material: OTHER OIL Quantity:

Potential Response Party

Company: VVEIRTON STEEL First Name: KEN

Last Name: ANDERSON

Type:

PRIVATE ENTERPRISE

Wednesday, July 24, 2013

Units:

0.00UNKNOWN

Please Note: This information is initial notification data and may be subject to verification.

Incident Notification No.:

**Incident Date:** 

554675 1/25/2001 Incident Type:

**FIXED** 

Incident Cause: **EQUIPMENT FAILURE** 

Incident Location

400 THREE SPRINGS DR.

Affected Medium

Medium: LAND

Waterway:

WEIRTON City\*:

Zip: 26062 County: HANCOCK State: WV

Tributary to:

Additional Medium Info: INSIDE THE BUILDING

\* Nearest City to Incident location is given. Incident may not have occurred within city borders.

Spilled Material:

First Name:

WASTE PICKLE LIQUOR

Quantity:

Units:

40.00GALLON(S)

Potential Response Party

ANTHONY Last Name:

Company: WEIRTON STEEL

Type:

PRIVATE ENTERPRISE

**Incident Notification No.:** 

576604

Incident Type:

STORAGE TANK

**Incident Date:** Incident Cause: **OPERATOR ERROR** 8/14/2001

**Incident Location** 

STAN

400 THREE SPRINGS DR.

Affected Medium

Medium: WATER

Waterway: HARMON CREEK

City\*: WEIRTON

Zip: 26062 County: HANCOCK State: WV

Tributary to:

OHIO RIVER

Additional Medium Info: HARMON CREEK

\* Nearest City to Incident location is given. Incident may not have occurred within city borders.

Spilled Material:

ROLLING OIL UNT

Quantity:

Units: 0.00UNKNOWN

Potential Response Party

First Name: KEN

WEIRTON STEEL Company:

ANDERSON Last Name:

Type:

PRIVATE ENTERPRISE

Incident Notification No.:

**Incident Date:** 

1037106

**FIXED Incident Type:** 

1/30/2013

**Incident Cause:** NATURAL PHENOMENON

Affected Medium

Incident Location

100 PENSILVIANA AVE

NULL **NULL** 

City\*: WEIRTON

26062 Zip: County: HANCOCK Medium: WATER

Waterway: HARMON CREEK

OHIO RIVER Tributary to:

Additional Medium Info: HARMON CREEK

\* Nearest City to Incident location is given. Incident may not have occurred within city borders.

Spilled Material:

Last Name: CAPRARESE

PROCESS WATER

State: WV

Quantity: 0

**UNKNOWN AMO** Units:

Potential Response Party

Company: ARCELLOR WEIRTON First Name: MATT

Type:

Please Note: This information is initial notification data and may be subject to verification.

Incident Notification No.:

Incident Date:

579714 9/13/2001

**FIXED** Incident Type: Incident Cause:

OTHER

Incident Location

400 THREE SPRINGS DRIVE

Affected Medium

Medium: WATER

Waterway: HARMON CREEK

WEIRTON City\*:

Zip: 26062

State: WV

County: HANCOCK

Tributary to: OHIO RIVER

Additional Medium Info: HARMON CREEK

\* Nearest City to Incident location is given. Incident may not have occurred within city borders.

Spilled Material:

MIXTURE OF WASTE OILS

Quantity:

Units: 0.00UNKNOWN

Potential Response Party

First Name: DAVID

Company: WEIRTON STEEL

Last Name: MINDA

Type:

PRIVATE ENTERPRISE

Incident Notification No.:

**Incident Date:** 

621817

Incident Type:

**FIXED** 

9/3/2002

**Incident Cause:** OTHER

Affected Medium

Incident Location 400 THREE SPRINGS DRIVE

Medium: WATER Waterway: STORM DRAIN

City\*: WEIRTON

Zip: 26062 State: WV

County: HANCOCK

Tributary to: WATER TREATMENT

Additional Medium Info: STORM DRAIN

\* Nearest City to Incident location is given. Incident may not have occurred within city borders.

Spilled Material:

First Name:

OIL, MISC: TRANSFORMER (PCB)

Quantity:

Units:

400.00GALLON(

DAVID

WEIRTON STEEL Company:

Potential Response Party

MINDA Last Name:

Type:

PRIVATE ENTERPRISE

Incident Notification No.:

Incident Date:

627126

**Incident Type:** 

FIXED

10/24/2002

**Incident Cause:** 

**EQUIPMENT FAILURE** 

Incident Location

400 THREE SPRINGS DRIVE

Affected Medium

Medium: WATER

Waterway: OHIO RIVER

WEIRTON City\*:

Zip: 26062

State: WV

MISSISSIPPI RIVER **Tributary to:** Additional Medium Info: OHIO RIVER

County: HANCOCK

\* Nearest City to Incident location is given. Incident may not have occurred within city borders.

OIL, FUEL: NO. 6

100.00GALLON( Units:

Spilled Material:

Quantity:

Potential Response Party

First Name:

JOE

Company: WEIRTON STEEL COMPANY

Last Name:

MCCAY

Type:

Please Note: This information is initial notification data and may be subject to verification.

Incident Notification No.:

**Incident Date:** 

871372 5/19/2008

Incident Type:

NULL

**FIXED** 

Affected Medium

Waterway: NULL

**EQUIPMENT FAILURE** Incident Cause:

Incident Location

100 PENNSYLVANIA AVENUE

NULL NULL

City\*: WEIRTON

County: HANCOCK

Zip: 26062 State: WV

Tributary to:

Medium: LAND

Additional Medium Info: ONTO THE GROUND

\* Nearest City to Incident location is given. Incident may not have occurred within city borders.

Spilled Material:

WASTE PICKLE ACID

Quantity: 900.00

Units:

GALLON(S)

Potential Response Party

Company: ARCELOR MITTAL WEIRTON

First Name: Last Name:

COLLINS

JOHN

Type:

PRIVATE ENTERPRISE

Incident Notification No.:

**Incident Date:** 

878805

Incident Type:

STORAGE TANK

Incident Cause: **EQUIPMENT FAILURE** 7/29/2008

Incident Location

100 PENNSYLVANIA AVE

NULL NULL

City\*: WEIRTON

Zip:

26062

State: WV

County: HANCOCK

Affected Medium

Medium: WATER Waterway: OHIO RIVER

**NULL** Tributary to:

Additional Medium Info: OHIO RIVER

\* Nearest City to Incident location is given. Incident may not have occurred within city borders.

Spilled Material:

OIL, FUEL: NO. 6

Quantity: 2100.00

Units: GALLON(S)

Potential Response Party

First Name: DAVID

Company: ARCELOR MITTAL

Last Name: MINDA

Type:

PRIVATE ENTERPRISE

**Incident Notification No.:** 

Incident Date:

882458 9/2/2008 Incident Type:

FIXED

Affected Medium

**EQUIPMENT FAILURE Incident Cause:** 

Incident Location

100 PENNSYLVANIA AVE.

NULL NULL

WEIRTON City\*:

26062 Zip:

County: HANCOCK

Medium: WATER

Waterway: HARMON CREEK

OHIO RIVER Tributary to:

Additional Medium Info: HARMON CREEK

\* Nearest City to Incident location is given. Incident may not have occurred within city borders.

PICKLING ACID Spilled Material:

Quantity: 200.00

GALLON(S) Units:

State: WV

JOHN

**Potential Response Party** WEIRTON STEEL CORP Company:

COLLINS Last Name:

First Name:

Type:

PRIVATE ENTERPRISE

Wednesday, July 24, 2013

Page 9

### Region III - Philadelphia PA

Please Note: This information is initial notification data and may be subject to verification.

Incident Notification No.:

Incident Date:

911735

**Incident Type:** 

**FIXED** 

Incident Cause: 7/16/2009 UNKNOWN

**Incident Location** 

100 PENNSYLVANIA AVENUE

NULL NULL

City\*: WEIRTON

Zip: 26062 State: WV

Affected Medium

Medium: WATER

Waterway: OHIO RIVER

N/A Tributary to:

Additional Medium Info: OHIO RIVER

\* Nearest City to Incident location is given. Incident may not have occurred within city borders.

Spilled Material:

TREATED WATER

Quantity: 0.00

Units: UNKNOWN AMO

County: HANCOCK

Potential Response Party

Company: ARCELOR MITTAL WEIRTON

**First Name:** Last Name:

COLLINS

JOHN

Type:

PRIVATE ENTERPRISE

Incident Notification No.:

Incident Date:

917263 9/9/2009 Incident Type:

**MOBILE** 

Incident Cause: **EQUIPMENT FAILURE** 

Affected Medium

Incident Location

3030 BIRCH DR.

NULL NULL

WEIRTON

City\*: Zip:

26062

State: WV

Waterway: NULL Medium: LAND

Potential Response Party

NULL Tributary to:

Additional Medium Info: ASPHALT (40FT X 20FT AREA)

County: HANCOCK

\* Nearest City to Incident location is given. Incident may not have occurred within city borders.

96X (FOOD COATING FROM VALSPAR CORP Quantity: 75.00 Spilled Material:

Units: GALLON(S)

First Name: NULL

QUALITY CARRIERS

Last Name: UNKNOWN

Type:

PRIVATE ENTERPRISE

Incident Notification No.:

Incident Date:

977322 5/25/2011

**Incident Type:** Incident Cause:

FIXED **UNKNOWN** 

100 PENNSYLVANIA AVENUE

**Incident Location** 

NULL

NULL

City\*: WEIRTON

First Name:

Zip: 26062 County: HANCOCK

State: WV

Affected Medium

Medium: WATER

Waterway: FACILITY'S OUTFALL

OHIO RIVER Tributary to:

Additional Medium Info: FACILITY'S OUTFALL

\* Nearest City to incident location is given. Incident may not have occurred within city borders.

HEXAVALENT CHROMIUM Spilled Material:

Quantity: 0.00

UNKNOWN AMO Units:

Potential Response Party Company: ARCELORMITTAL WEIRTON

MINDA Last Name:

DAVE

Type:

### Region III - Philadelphia PA

Please Note: This information is initial notification data and may be subject to verification.

**Incident Notification No.:** 

986684

**Incident Type:** 

**FIXED** 

Incident Date:

8/21/2011

Incident Cause:

**EQUIPMENT FAILURE** 

Waterway: OHIO RIVER

**Incident Location** 

403 SPRING DRIVE

NULL NULL

City\*: WEIRTON

County: HANCOCK

Zip:

26062

State: WV

Affected Medium

NULL Tributary to:

Medium: WATER

Additional Medium Info: OHIO RIVER

\* Nearest City to Incident location is given. Incident may not have occurred within city borders.

WASTE OIL Spilled Material:

Quantity: 0.00

Units: UNKNOWN AMO

Potential Response Party

First Name: MIKE

Company:

METTAL WEIRTON STEEL

Last Name: DZIATKOWICZ

Type:

PRIVATE ENTERPRISE

Incident Notification No.:

**Incident Date:** 

567171

Incident Type:

**PIPELINE** 

5/24/2001

Incident Cause: OTHER

**Incident Location** 

400 THREE SPRINGS DR.

Affected Medium

Medium: BALLAST

Waterway:

WEIRTON City\*:

County: HANCOCK

Zip:

26062

State: WV

Tributary to:

Additional Medium Info: GRAVEL

\* Nearest City to incident location is given. Incident may not have occurred within city borders.

Spilled Material:

WASTE PICKLE LIQUOR

Quantity:

50.00GALLON(S) Units:

Potential Response Party

First Name:

GARY

Company:

WEIRTON STEEL

Last Name: DOAK

Type:

### Region III, Philadelphia PA

\*\*\*\*\* Please note that this is initial notification data and may be subject to verification. \*\*\*\*\*

			a card may be se		
Regional Case Number	Potential Responsible party	Spilled Material		Quantity	Spill Date
WV990279	WEIRTON STEEL CORP	1) WASTE PICKLE LIQUOR		2000 G	9/27/1999
NRC Number	ricidant location	2) 3)		0 0	
	4)0 THREE SPRINGS DRIVE VIEIRTON WV COUNTY: HANCOCK	<b>Zip:</b> 26062	Medium Affected W	×	
SOURCE	CAUSE	<b>S</b>	WATERWAY	SOIL>PLANT SEWER	
WV990278	WEIRTON STEEL	1) WASTE PICKLE LIQUOR		n o	9/27/1999
NRC Number	house a boundarisemen	2)		0 0	
500228	Incident Location			)	
	400 3 SPRINGS DR.				
	V/EIRTON WV ZI	<b>p:</b> 26062	Medium Affected	<b>^</b>	
SOURCE	CAUSE	, LL	WATERWAY	HARMON CREEK/OHI	
WV990207	WEIRTON STEEL CORPORATION		(8.1MG PER PEP KG)	0 0	6/15/1999
NRC Number 487590	Incident Location	3) BENZO (B) FLUORANTHENE (6.4MG PE	VE (6.4MG PE	0 0	
	E SPRINGS DRIV				
	WEIRTON WV COUNTY: BROOKE, HANCOCK	<b>Zip:</b> Z6U6Z	Medium Affected		
SOURCE	CAUSE	Α .	WATERWAY	NONE	

Page 1

### Region III, Philadelphia PA

	***** Please note	***** Please note that this is initial notification data and may be subject to verification. *****	bject to verification. *****	
Regional Case Number	Potential Responsible	lled Material	Quantity	Spill Date
WV990207	WEIRTON STEEL CORPORATION	1) BENZO (A) ANTHRACENE (8.1MG PER	Π 0	6/15/1999
;	and constraints are constraints and constraint	2) BENZO (A) PYRENE (6MG PER KG)	n o	
NRC Number		3) BENZO (B) FLUORANTHENE (6.4MG PE	N 0	
46/080	Incident Location			
	2	C3030		
		Zip: Zouoz Medium Affected	-	
SOURCE	F CAUSE	D WATERWAY	NONE	
WV990083	WEIRTON STEELE	1) OILS.MISC:TRANSFORMER	12 G	1/25/1999
			0	
NRC Number	· · · · · · · · · · · · · · · · · · ·	` Œ	C	
471768	Incident Location		)	
	400 3 SPRINGS DR.			
	WEIRTON	WV <b>Zip</b> : 26062		
	COUNTY: BROOKE, HANCOCK	Medium Affected		
SOURCE	F	F WATERWAY	NONE	
	I	4) OU CAMEOTTDANICEODMED	, ,	1/25/1999
000088			) )	
NRC Number			<b>&gt;</b> C	
471768	Incident Location	(î	o	
	400 3 SPRINGS DR.			
	WEIRTON WV Zip:	<b>Zip:</b> 26062		
	COUNTY: BROOKE, HANCOCK	Medium Affected	1	
SOURCE	CAUSE	F WATERWAY	NONE	
		4		

Page 2

### Region III, Philadelphia PA

****
rerification.
5
Ç
£bje
ระ
ğ
пау
ξ
ä
data aı
notification data and may k
i a
this is initial no
<u>0</u>
t)
e that
e #
not
Se
*** Please note
**** Ple
***

	***** Please n	**** Please note that this is initial notification data and may be subject to verification.	data and may be su	abject to ver	ification, ****	
Regional Case Number	Potential	of Material		1	Ousofifty	Spill Date
2000	Responsible party	Spilled Material			Qualitity	opiii Date
WV990026	WEIRTON STEEL CORP	1) SPENT PICKLE LIQUOR	~		200 G	11/5/1998
		2)			0	
NRC Number		(6)			c	
462768	Incident Location				Þ	
	400 THREE SPRINGS DRIVE					
	WEIRTON	WV Zip: 26062				
	COUNTY: BROOKE, HANCOCK	OCK	Medium Affected	<b></b>		
SOURCE	F CAUSE	iL.	WATERWAY	NONE		
WV990026	WEIRTON STEEL CORP	1) SPENT PICKLE LIQUOR	ſY.		200 G	11/5/1998
		2)			0	
NRC Number	· · · · ·	3)			C	
462768	Incident Location				Þ	
	400 THREE SPRINGS DRIVE					
	WEIRTON	WV Zip: 26062				
	COUNTY: BROOKE, HANCOCK	OCK	Medium Affected			
SOURCE	F	ட	WATERWAY	NONE		
WV980338	WEIRTON STEEL	1) WASTE PICKLE LIQUOR	<b>~</b>		1000 G	8/13/1998
	200	2)			0	
NRC Number		3)			С	
450459	Incident Location				•	
	400 3 SPRINGS DR.					
	WEIRTON	WV <b>Zip</b> : 26062				
	COUNTY: BROOKE, HANCOCK	OCK	Medium Affected			
SOURCE	CAUSE	ם	WATERWAY	NONE		

Page 3

### Region III, Philadelphia PA

energy ordered	**** Please not	***** Please note that this is initial notification data and may be subject to verification *****	ata and may be su	bject to verification. ****	
Regional Case Number	Potential Responsible party S	Spilled Material		Quantify	Spill Date
WV980164	WEIRTON STEEL	1) HYDROCHLORIC ACID		1500 G	2/23/1998
NPC Number		2)		0 0	
425705	Incident Location	3)		Þ	
	400 3 SPRINGS DR.				
		WV <b>Zip</b> : 26062	:	;	
***************************************	COUNTY: BROOKE, HANCOCK	×	Medium Affected W	^	
SOURCE	F CAUSE	ш.	WATERWAY	HARMON CREEK	
WV980115	WEIRTON STEEL	1) HYDRAULIC OIL		2000 G	1/29/1998
		2)		0	
NRC Number		3)		0	
421961	Incident Location				
	400 3 SPRINGS DR.				
	WEIRTON	WV <b>Zip:</b> 26062	:	:	
	COUNTY: BROOKE, HANCOCK	×	ğ	^	
SOURCE	F	0	WATERWAY	HARMON CREEK	
		4) HYDROCHI OBIC ACID		1000 G	9/11/1997
85507874	WEIN ON FOLL CONT.			C	
NRC Number		. (2		0	
403137	Incident Location				
reconstruction.	E SPRINGS DRIV	i			
	WEIRTON WV COLINTY: BROOKE HANCOCK	<b>21p:</b> 28u82 X	Medium Affected	k	
SOURCE		ட	WATERWAY	NONE	

Page 4

### Region III, Philadelphia PA

***** L
erification
e subject to v
lata and may b
fication dat
s initial noti
e that this i
** Please not
***

	Fiease note th	e that this is initial notification data and may be subject to verification.	data and may be su	plect to verification, """	
Regional Case Number	Potential Responsible party	Spilled Material		Quantity	Spill Date
WV94429	WEIRTON STEEL	1) SULFURIC ACID		9 009 200 G	7/26/1994
NDC Mumbo		2)		0	
054744		3)		0	
11.7167	400 THREE SPRINGS DRIVE				
	WEIRTON	WV <b>Zip:</b> 26062			
	COUNTY: HANCOCK		Medium Affected	_	
SOURCE	CAUSE	<b>LL</b> .	WATERWAY	NONE	
					0007077
WV94203	WEIRTON STEEL	1) UNKNOWN OIL		O 0	C881/71/11
		2)		0	
NKC Number		3)		0	
207626	Incident Location	î		ŧ	
	400 THREE SPRINGS DRIVE				
	WEIRTON	<b>Zip:</b> 26062			
	COUNTY:		Medium Affected	Μ	
SOURCE	CAUSE		WATERWAY	OHIO RIVER MILE MA	
WV93376	WEIRTON STEEL	1) ZINC CYANIDE PLATING SOLUTION	G SOLUTION	4000 G	7/14/1993
NRC Number	mi-wiji siya	2)		0 (	
186197	Incident Location	3}		o	
	400 THREE SPRINGS DRIVE				
	WEIRTON	<b>Zip:</b> 26062			
	COUNTY: HANCOCK		Medium Affected WF	WF	
SOURCE	F CAUSE	LL.	WATERWAY	TREATMENT PLANT -	

Page 6

### Region III, Philadelphia PA

. come 6 7 7 6 1	***** Please not	**** Please note that this is initial notification data and may be subject to verification. ****	ata and may be su	bject to verification, *****	
Regional Case Number	Potential Responsible	Spilled Material		Quantity	Spill Date
WV93361	WEIRTON STEEL	1) WATER WITH TIN PLATER SOLUTION	R SOLUTION	N 0	7/6/1993
NRC Milmhar		2)		0	
255100000000000000000000000000000000000	Incident Location	3)		0	
	400 THREE SPRINGS DRIVE				
	WEIRTON	WV <b>Zip:</b> 26062			
	COUNTY: HANCOCK		Medium Affected	×	
SOURCE	F	0	WATERWAY	WASTE WATER TREA	
		NOIFI 100 OMITY IS MIT A		()	6/15/1993
VV V 9 5 5 4 5	VEIRION OF EEL	THE PLATING SOLUTION		5 000I	6
		2)		0	
NKC Number		3)		0	
180523	Incident Location				
	400 THREE SPRINGS DRIVE				
	WEIRTON	<b>Zip:</b> 26062			
	COUNTY: HANCOCK		Medium Affected	M	
SOURCE	F	Ш	WATERWAY	OUTFALL TO OHIO RI	
WV93296	WEIRTON STEEL MILL	1) UNKNOWN MATERIAL		0	5/17/1993
- verenget (Ind. V.)		2)		0	
NRC Number		3)		0	
174103	Incident Location				
	UNKNOWN				
	WEIRTON	WV <b>Zip:</b> 26062			
	COUNTY: BROOKE		Medium Affected	V	
SOURCE	F	_	WATERWAY	NONE	

Page 7

### Region III, Philadelphia PA

\*\*\*\*\* Please note that this is initial notification data and may be subject to verification, \*\*\*\*\*

	***** Please no	***** Please note that this is initial notification data and may be subject to verification. *****	ata and may be su	ubject to verification, *****	
Regional Case Number	Potential Responsible party	Spilled Material		Quantity	Spill Date
WV93275	WIEIRTON FIELD CORP.	1) WASTE WATER TREATMENT SLUDGE	TENT SLUDGE	9 009	4/29/1993
NRC Number	antinorphism (children)	3) (2)		00	
170428	Incident Location	()		<b>5</b>	
	400 THREE SPRINGS DR.				
	WIEIRTON	/ <b>Zip:</b> 26062			
	COUNTY: HANCOCK		Medium Affected	Μ	
SOURCE	F	LL.	WATERWAY	STORM SEWER	
				( ( ( ( ( ( ( ( ( ( ( ( ( ( ( ( ( ( ( (	414414003
WV93146	WEIRTON STEEL CORP.	1) TIN PLATING SLUDGE		200 G	17 14/ 1985
		2)		0	
NKC Number		ලි		0	
153448	Incident Location				
	400 THREE SPRINGS DR.				
	WEIRTON	/ <b>Zip:</b> 26062			
	COUNTY: HANCOCK		Medium Affected	<b>*</b>	
SOURCE	CAUSE	ш	WATERWAY	OHIO RIVER MM 66.7	
WV93036	WEIRTON STEEL	1) UNKNOWN		0	10/23/1992
				C	
NRC Number		) (ñ		c -	
141681	Incident Location			,	
	MAIN ST.				
	WEIRTON WV	/ <b>Zip:</b> 26062	:		
	COUNTY: HANCOCK		Medium Affected	⋖	
SOURCE	F CAUSE	n	WATERWAY	NONE	

Page 8

### Region III, Philadelphia PA

	***** Please no	***** Please note that this is initial notification data and may be subject to verification. ****	be subject to verification. *	****	
Regional Case Number	Potential Responsible	Spilled Material	Quantity	<i>*</i> :	Spill Date
WV92454	WEIRTON STEEL CORP	1) HALOGEN TIN PLATING SOLUTION	4000	4000 G	9/25/1992
NRC Number		2)		0 (	
138246	Incident Location	3)		0	
	400 THREE SPRINGS DR.				
	WEIRTON	, <b>Zip</b> : 26062			
	COUNTY: HANCOCK	Medium Affected	cted L		
SOURCE	F	O WATERWAY	NONE		
WV92355	WEIRTON STEEL	1) WASTE WATER FROM PLANT		<b>⊃</b>	7/15/1992
NRC Number		2)		0	
126754	Incident Location	3)		0	
	400 THREE SPRINGS DRIVE				
	WEIRTON	/ <b>Zip:</b> 26062			
	COUNTY: HANCOCK	Medium Affected W	cted W		
SOURCE	F	N WATERWAY	OHIO RIVER		
WV92329	WEIRTON STEEL	1) BLAST FURNACE WATER	J	n 0	6/28/1992
NRC Number	no programa na	2)		0 0	
123964	Incident Location				

Page 9

Wednesday, July 24, 2013

**OUTFALL TO SETTLIN** 

Medium Affected W

WV Zip: 26062

400 THREE SPRINGS DR.

Incident Location

123964

COUNTY: HANCOCK

SOURCE

WEIRTON

WATERWAY

### Region III, Philadelphia PA

****
ion.
icat
/erif
ţo.
ject
qns
pe
data and may b
and
lata a
n dâ
atio
tific
l no
nitia
: <u>:</u>
this
hat
note that
ou e
Pleas
d ****

Regional	Q		•	•		
Case Number	Responsible party	Spilled Material			Quantity	Spill Date
WV92320	WEIRTON STEEL CORP.	1) TIN PLATING SOLUTION			7000 G	6/25/1992
		2)			0	
ACIUMN AND		3)			0	
173671	incident Location					
- central 10° 20°	400-THREE SPRINGS DR.					
e nergy Parket	WEIRTON	<b>Zip:</b> 26062				
	COUNTY: HANCOCK		Medium Affected	ĹĽ		
SOURCE	F CAUSE	Ŀ	WATERWAY	NONE		
		ACT TO CALL				5/27/1992
81778AM	WEIKLON STEEL	1) PLATING SOLUTION			3000 G	70011770
NRC Number		2)			0 0	
119227	Incident Location	(î			>	
	400 THRFF SPRINGS DR					
· certació		i				
, com 23/24/o	WEIRTON	<b>Zip:</b> 26062				
	COUNTY: HANCOCK		Medium Affected	ш.		
SOURCE	CAUSE	LL.	WATERWAY	NONE		
WV92221	WEIRTON STEEL (SUSPECT)	1) UNKNOWN/SMELL IN THE AIR	1E AIR		n o	4/6/1992
NPC Nimbo		2)			0	
		3)			0	
113081	Incident Location					
- congress of Publish	UNSPECIFIED					
y ennefelik j	WEIRTON	<b>Zip:</b> 26062				
	COUNTY: HANCOCK		Medium Affected A	A		
SOURCE	U CAUSE	D	WATERWAY	NONE		
	Did selving a					

Page 10

### Region III, Philadelphia PA

****
erification.
9
ct t
Ρ̈́
su
pe
ay
E
data and
ţ
q
tification
cat
ij
2
is initial
Ξ
<u>છ</u>
Ø
that thi
Ë
note
еп
as
* Please I
****

		ives note that the second include the second second second section	and and may be o	abject to verification:	
Regional Case Number	Potential  Responsible party	Spilled Material		Quantity	Spill Date
WV92025	WEIRTON STEEL CORP.	1) WASTEWTR W/OIL MAT. ON TOP	ON TOP	750000 G	10/24/1991
		2)		0	
NRC Number		3)		C	
93573	Incident Location			)	
energy would have	400 THREE SPRINGS DR.				
	WEIRTON	WV Zip: 26062			
received (See	COUNTY: BROOKE, HANCOCK	CK	Medium Affected W	^	
SOURCE	CAUSE	ΙĽ	WATERWAY	OHIO RIVER MILE 63	
WV91338	WEIRTON STEEL CORP.	1) WASTE WATER		235000 G	6/7/1991
e en esta de la compania de la comp		2)		0	
NKC Number	•	3)		C	
74851	Incident Location	î		)	
	400 THREE SPRINGS DR.				
en e	WEIRTON	WV <b>Zip:</b> 26062			
e en la	COUNTY: HANCOCK		Medium Affected	<b>*</b>	
SOURCE	F CAUSE	ш	WATERWAY	OHIO RIVER	
WV91296	WEIRTON STEEL CORP.	1) OIL, FUEL: NO. 6		5 G	5/18/1991
e e y y e e e y e e e e		2)		0	
NRC Number		3)		0	
72523	Incident Location 400 THREE SPRINGS DR				
erene er	•	WV <b>Zip</b> : 26062			
a kiri kiriki	COUNTY: BROOKE, HANCOCK	ÕΚ	Medium Affected W	W	
SOURCE	CAUSE	ш	WATERWAY	OHIO RIVER MILE PO	

Page 11

### Region III, Philadelphia PA

***
verification.
ubject to
data and may be s
ification dat
s initial not
e that this i
** Please note
***

el libertheven	***** Please no	***** Please note that this is initial notification data and may be subject to verification. ****	ita and may be su	ubject to verification. ****	
Regional Case Number	Potential Responsible	Spilled Material	,	Quantity	Spill Date
WV89435	SUSPECT: WEIRTON STEEL	1) UNKNOWN SUBSTANCE IN THE AIR	IN THE AIR	Π 0	8/30/1989
e grande e		2)		0	
NRC Number		· 6		C	
15370	Incident Location			)	
ggagani kandul	S. MAIN STREET				
	WEIRTON, HANCOCK WV	/ <b>Zip:</b> 26062			
toria e e e e e e e e e e e e e e e e e e e	COUNTY:		Medium Affected	A	
SOURCE	FCAUSE	n	WATERWAY	NONE	
WV88354	WEIRTON STEEL CORP.	1) HYDROCHLORIC ACID		0	8/23/1988
		2)		0	
NRC Number	•	ଜ		C	
11667	Incident Location	õ		)	
, deliver e e e e	400 THREE SPRING DR.				
·	WEIRTON	WV <b>Zip:</b> 26062			
metrical with divines	COUNTY: BROOKE, HANCOCK	X	Medium Affected	M	
SOURCE	F CAUSE	£L.	WATERWAY	HARMON CREEK TO	
WV88107	WEIRTON STEEL	1) WASTE PICKLE LIQUOR			1/19/1988
NEC Number		2)		0	
774	Incident Location	3)		0	
	IGS DRIV				
zinenia (sa den	WEIRTON	/ <b>Zip:</b> 26062	:	;	
and the state of t	COUNTY: BROOKE, HANCOCK	X	Medium Affected	>	
SOURCE	F CAUSE	LL.	WATERWAY		

Page 12